


37 CUBE LOW VOLTAGE





Assembly instructions Y503-11528 rev 0.1



Attention: Read and understand these instructions before installing fixture. This fixture is intended for installation in accordance with National Electric Code and local regulation: To assure full compliance with local codes and regulations, check with your local electrical inspector before installation. This equipment is guaranteed only when used as indicated in these instructions; therefore they should be kept for future reference. To prevent electrical shock, turn off power supply before carrying out any connection or maintenance operations.










STEP 2A


For Low-volatage wires :

- 1. Pass wire through bushing.
- 2. pass inside strain relief and tighten the screws



STEP 3


- 1. Make appropriate connections.
- 2. Screw junction box cover back.



STEP 2B

For BX conduit or Loomex wires:

- 1. Remove bushing, screws and strain relief bracket
- 2. Install BX conduit or loomex connector (not included).





37 CUBE LOW VOLTAGE



Assembly instructions Y503-11528 rev 0.1

